POWER SUPPLY SCHEMATIC

Revised August 8 2005



BY PLACING A MILLI-VOLTMETER ACROSS "RS" AND CALIBRATING IT, OUTPUT CURRENT CAN BE MEASURED WITHOUT ANY LOSS IN VOLTAGE.

THESE POINTS AND NUMBERS
12
REPRESENT THE ORIGIONAL IC PIN NUMBERS.

OPTIONAL MODE INDICATOR

OPTIONAL

HIGH CURRENT DRIVE.

OPTIONAL

EVEN HIGHER CURRENT DRIVE