



4. ADDED AS SECONDARY OPERATION.
 2. ALL CAPACITORS IN MICROFARADS, EXCEPT AS NOTED.
 1. ALL RESISTORS IN OHMS

NOTES: UNLESS OTHERWISE SPECIFIED.

CARVIN		12340 World Trade Drive San Diego, CA 92128 (858) 487-1600 FAX 521-6032	
DRAWN BY: GEORGE DREYER		DATE: 10JUNE97	
APPROVED:		DATE:	
PCB NO: 30-40600	REV: N		
ASSY: 80-40626	REV: N		
NO: 80-41000	REV: N		
REVISED BY: GEORGE DREYER	DATE: 11October2000		

- CHANGES FOR R1000 ASSEMBLY: 80-41000
1. Add Q110, Q210 (Type: MJL 21194).
 2. Add Q114, Q214 (Type: MJL 21193).
 3. Add R168-R175, R268-R275 (0.22 Ω).
 4. Change C501, C502 to 10Kmf @ 80V.

- Changes from Assembly Rev (H3).
1. Revised jacks to front panel.
 2. Revised header numbering.
 3. Revised PCB to Rev (G).
- Changes from Assembly Rev (H4).
1. Moved Clip LEDs to Front PCB:D103, D203.
 2. Revised headers H3 & H14.
 3. Revised PCB to Rev (H).
- Changes from Assembly 80-41000 Rev (I).
1. R519 from 100 Ω to 36 Ω .
- Changes from Assembly 80-41000 and 80-40626 Rev (J&L).
1. C28 from .022u to .033u.
- Changes from Assembly 80-41000 and 80-40626 Rev (J1).
1. total change to new power amp, SMT and Speakers.
- Changes from PCB 3040626 Rev (J).
1. power amp protection changes.
- Changes from PCB 3040626 Rev (K).
1. balance main header connections.
 2. split graphic EQ and use parallel connection.
- Changes from PCB 3040626 Rev (L).
1. power amp DC output protection added.
 2. split graphic EQ to series connection.
- Changes from PCB 3040626 Rev (M).
1. PCB updated.
 2. Q106 & Q206 updated packaging.

