



# H MOTOR P.C.B.



# N AC IN P.C.B.



## ELECTRICAL PARTS LOCATION

Ref. No.	Lo. No.	Ref. No.	Lo. No.	Ref. No.	Lo. No.	Ref. No.	Lo. No.
<b>H MOTOR P.C.B.</b>							
IC1	3C	S2	4B	W2	4C	C2	2B
Q1	4C	S3	3C	RM1	2B		
D2	4C	CN1	4C	R1	3C		
S1	3B	W1	5C	C1	2C		
<b>N AC IN P.C.B.</b>							
T502	2D	F1	2F	W5	5F	W9	4F
S501	4E	F2	3F	W6	5E	W10	4F
Z501	2E	CN500	2E	W7	5F	JK500	4D
PL1	3F	W1A	2F	W8	4F		

