

SECTION 2 ELECTRICAL ADJUSTMENTS

Bias Adjustment

Note: Adjustment the idling after tuning the unit on for about 10 minutes, giving it time to warm up.

Procedure :

1. Connect the digital voltmeter to VH4 on main board as follows.
2. Adjust RT301(L-CH) and RT351(R-CH) so that the digital voltmeter on signal reads 24mV at VH4.

Adjustment Location :

[MAIN BOARD]

— COMPONENT SIDE —

