

VCDS

Windows Based VAG/VAS Emulator Running on Windows 7 x86  
VCDS Version: Release 21.3.0 Data version: 20210226 DS325.0  
www.Ross-Tech.com

Dealer/Shop Name:  
Workshop Code: 000 00000 000000

Self-Diagnosis Log  
Friday, 17, September, 2021, 09:49:39:00009

VIN: WAUZZZ8Z13N009248 License Plate:  
Mileage: 317150km-197067mi Repair Order:

Chassis Type: 8Z (8Z - Audi A2 (2000 > 2005))  
Scan: 01 02 03 08 15 16 17 18 37 45 46 56 57 75 76 77

VIN: WAUZZZ8Z13N009248 Mileage: 317150km-197067miles

---

Address 01: Engine Labels: 045-906-019-AMF.clb  
Part No: 045 906 019 G  
Component: 1,4l R3 EDC 0000SG 1514  
Coding: 00002  
Shop #: WSC 02138  
VCID: 193390A68399BB4324-4B18  
WAUZZZ8Z13N009248 AUZ7Z0B2151444

1 Fault Found:  
18062 - Please check DTC Memory of Instrument Cluster  
P1654 - 35-00 -  
Readiness: 0 0 X X X

---

Address 03: ABS Brakes Labels: 8Z0-907-379-MK60.lbl  
Part No: 8Z0 907 379 C  
Component: ESP FRONT MK60 0101  
Coding: 0019591  
Shop #: WSC 02154 785 00200  
VCID: 489505E238B3F2CB4B-515A

No fault code found.

---

Address 08: Auto HVAC Labels: None  
Part No: 8Z0 820 043 E  
Component: A2-KLIMAVOLLAUTOMAT 0512  
VCID: 387575221853824B3B-258C

2 Faults Found:  
01271 - Positioning Motor for Temperature Flap (V68)  
41-10 - Blocked or No Voltage - Intermittent  
00727 - Potentiometer in Positioning Motor for Defrost Flap (G135)  
30-00 - Open or Short to Plus

---

VIN: WAUZZZ8Z13N009248 License Plate:

Address 15: Airbags Labels: 8Z0-959-655.lbl  
Part No: 8Z0 959 655 E  
Component: Airbag Front+Seite 5005  
Coding: 00102  
Shop #: WSC 02152  
VCID: 4E9933FA8AD72CFB01-515A

No fault code found.

-----  
Address 17: Instruments Labels: 8Z0-920-xxx-17.lbl  
Part No: 8Z0 920 900 T  
Component: KOMBI+WEGFAHRS. VDO D02  
Coding: 08130  
Shop #: WSC 00186  
VCID: 4A913FEA76BF00DB5D-515A  
WAUZZZ8Z13N009248 AUZ7Z0B2151444

2 Faults Found:  
00562 - Sensor for Oil Level/Temperature (G266)  
27-10 - Implausible Signal - Intermittent  
00816 - Power Steering Sensor (G250)  
36-00 - Open Circuit

-----  
Address 18: Aux. Heat Labels: None  
Part No: 8Z0 815 071  
Component: Zuheizer Diesel D49  
Coding: 00002  
Shop #: WSC 02138  
VCID: 78F5B52258D3424BFB-4BB0

No fault code found.

-----

VCDS  
Self-Diagnosis Log  
Friday, 17, September, 2021, 09:49:39:00009  
Page 3

VIN: WAUZZZ8Z13N009248 License Plate:

Address 46: Central Conv. Labels: . 8Z0-959-433.lbl  
Part No: 8Z0 959 433 AC  
Component: Komfortgerát TA5 1210  
Coding: 06720  
Shop #: WSC 02138  
VCID: 0717C6DE252D3DB382-4B32

Subsystem 1 - Part No: 8Z1959801A  
Component: Tórsteuer.FS BRM 0003

Subsystem 2 - Part No: 8Z1959802A  
Component: Tórsteuer.BF BRM 0003

3 Faults Found:

01562 - Rear right door  
59-10 - Can't Unlock - Intermittent  
01562 - Rear right door  
61-00 - Won't De-Safe  
01366 - Opened Due to Crash Signal  
35-00 --

End----- (Elapsed Time: 04:07) -----