



USB+

JNH

LM 1036M

J41

J40

LM 1036M

R1

C1

C12

C5

C6

C30

C10

R6

C11

R2

R4

C3

C4

R10

C

R41

R21

C2

I01

1

C23

I02

1

C7

+

R5

C27

+

R25

C33

+

R24

R23

C8

+

C24

+

C25

+

C40

+

C26

A

C20

B

R30

R7

C32

R20

R40

P1

P2

P3

P4