


KABEL-TUNER 29504-101.01
 CABLE TV TUNER
 TUNER TV CAVO
 -101.02
 -101.06
 -101.10
 -181.01

Kein Anpassungsabgleich bei Austausch der Steckkarte notwendig
 When replacing the plug-in board, no alignment is necessary
 Non è necessaria nessuna taratura di adattamento dopo la
 sostituzione di una scheda ad innesto



	CT2010	CC2030	CC2105	CC2106
-101 01	BF996	15P	39P	27P
-101 02	BF996	15P	39P	27P
-101 06	BF996	15P	39P	27P
-181 01	BF998	8.2P	27P	39P
-101 10	BF996	15P	39P	27P