



IMPORTANT SAFETY NOTICE
 THE SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION, FIRE AND ELECTRICAL SHOCK HAZARDS. WHEN SERVICING IT IS ESSENTIAL THAT ONLY MANUFACTURER SPECIFIED PARTS BE USED FOR THE CRITICAL COMPONENTS IN THE SYMBOL MARK OF THE SCHEMATIC.

	SYMBOL	VALUE	UNIT
X	NORMAL	H	1.5KV
	STAND-BY	L	HEATER ON
	OFF	L	HEATER OFF
		3W	

NOTICE
 Since this is a basic schematic diagram, the value of components and some partial connection are subject to be changed for improvement without notice.